

Oil Field Environmental Incident Summary

Incident: 20150123160748 **Date/Time of Notice:** 01/23/2015 16:07

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: BARNEY 5-29H-2

Field Name: BROOKLYN

Well File #: 24378

Date Incident: 1/23/2015

Time Incident: 02:30

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 98

Sec: 29

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
PO Box 268835
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	4.8	Barrels	5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/23/2016

Clean Up Concluded: 1/25/2015

Risk Evaluation:

None

Areal Extent:

Spill mostly contained to bermed tank battery, with 1 gallon outside on snow.

Potential Environmental Impacts:

Minimal

Action Taken or Planned:

Standing fluid was sucked up and impacted material was taken to disposal.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved: Notified Tami Cook NDIC by phone on 1/23/2015 at 3:56 PM CT.

Updates

Date: 1/26/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.